

Form 9-331a  
(March 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las CrucesLease No. 034075-A

Unit .....

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO <del>REPAIR</del> OR REPAIR WELL.....	<b>X</b>	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, September 10, 19 45C. J. SaundersWell No. 4 is located 1980 ft. from S line and 1980 ft. from W line of sec. 18NE 1/4 SW 1/4, Sec. 18 19-S 37-E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Monument

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3708 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was completed August 14, 1937, with an initial production of 46 barrels of oil per hour after a 2000-gallon acid treatment. Recently, the well has started producing water, and at the present time water out is between 8% and 10%. This well was drilled to total depth of 4030' or 322' sub-sea, and is 18' deeper than any other well on the lease. Since none of the other wells produce water, we desire to plug this well back 10' to 20', using plastic, in order to shut off the water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company THE TEXAS COMPANYAddress Box 1270Midland, TexasBy L. E. ShultzTitle District Superintendent