STA'E OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

HO. D' COPIES DECEIVED	
DISTRIBUTION	
SANTA PE	
FILE	
U.S.G.S.	
LAND OFFICE	
05201702	

work) SEE RULE 1103.

UIL CONSERVATION DIVISION P. O. BOX 2088

Form	c-	103	
Revis	ed	10 -	1 - 7

SANTA FE, NEW MEXICO 87501 5a. Indicate Type of Lease State Foo X 5. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS TO DE HOT USE THIS FORM FOR PROPOSALS TO DE HILL ON TO DEEPEN OR PLUG BACK TO A E USE "APPLICATION FOR PERMIT _" (FORM C-101; FOR SUCK PROPOSA 7. Unit Agreement Name WELL WELL 8. Farm or Lease Name 2. Name of Operator Gulf Oil Corporation B. V. Culp (NCT-A)
9. Well No. 3. Address of Operator P. O. Box 670, Hobbs, NM 10. Field and Pool, or Wildcat 4. Location of Well 1980 FEET FROM THE NOrth LINE AND UNIT LETTER __C _19 **19**S 15. Elevation (Show whether DF, RT, GR, etc.) 12. County 3687' DF Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON COMMENCE DRILLING OPHS. PLUG AND ABANDONMEN CASING TEST AND CEMENT JOB PULL OR ALTER CASING Hydromite Plug Back

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

POH with rods and tubing. Dumped 128 gals hydromite, new PBTD 3877. RIH with tubing subs, SN, working barrel, 2-3/8" tubing; land tubing 3866.91 and SN 3856.05. RIH with rods, hung well on. Prior to plug back, pumped 10 BO, 560 BW w/approx 40 MCF gas in 24 hours; after plug back, pumped 126 BO, 7 BW w/approx 165 MCF gas in 24 hours. Complete after hydromite plug back 8-11-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 8-13-81 Orly. Signal h Les Clements THE ORS INSP CONDITIONS OF APPROVAL, IF AN