

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION


P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-05642

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)



7. Lease Name or Unit Agreement Name
NORTH MONUMENT G/SA UNIT
BLK. 5

1. Type of Well:
OIL WELL GAS WELL OTHER INJECTION

8. Well No.
5

2. Name of Operator
Amerada Hess Corporation

9. Pool name or Wildcat
EUNICE MONUMENT G/SA

3. Address of Operator
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location
Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line
Section 19 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING
OTHER: CONVERT TO INJECTION WELL.

REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #505
MIRU PU & REVERSE UNIT. TOH LAYING DWN. RODS & PUMP. ND WELLHEAD. NU BOP. TOH W/TBG. TIH W/RBP & SET @ +/-500'. INSTALL NEW WELLHEAD EQUIP. TIH W/TBG. & RETRIEVE RBP. TOH W/RBP. RU WIRELINE CO. & STRING SHOOT O.H. W/400 GR/FT. TO RMV. BARIUM SCALE. CHK. FOR FILL. CLEAN OUT IF NECESSARY. RU SCHLUMBERGER. LOG THE O.H. W/SONIC/CNL/GR/CCL TOOLS. RD SCHLUMBERGER. RU CEMENTERS. TIH W/TBG. O.E. & SPOT CMT. PLUG FR. 4,028'-3,995'. (USE OYSTER SHELLS TO EST. CIRC. IF NECESSARY). WOC 24 HRS. EVALUATE FOR COMMUNICATION W/SAN ANDRES. TIH W/SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/5,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. @ +/-3,625'. SWAB/FLOW BACK LOAD. TOH W/TBG. & PKR. LAYING DWN. PROD. TBG. PU & TIH W/2-3/8" LINED INJ. TBG. W/INJ. PKR. ND BOP. NU INJ. WELLHEAD ASSEMBLY. RDMO PU. CLEAN & CLEAR LOCATION. OBTAIN STATIC BTM. HOLE PRESS. BEFORE BEGINNING INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 08/19/96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL FILED BY TERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 20 1996

CONDITIONS OF APPROVAL, IF ANY: