

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDARY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Chevron U.S.A. Inc.

Address of Operator

P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 19 TOWNSHIP 19S RANGE 37E N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name

B.V. Culp (NCT-A)

9. Well No.

2

10. Field and Pool, or Wellhead

Eunice Monument Gb-2A

15. Elevation (Show whether DF, RT, GR, etc.)

3704

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:ORM REMEDIAL WORK ☐
FORABLY ABANDON ☐
OR ALTER CASING ☐PLUG AND ABANDON ☐
CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐ALTERING CASING ☐
PLUG AND ABANDONMENT ☐OTHER perf/acdz ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 4040 PB: 4028 Work performed 2-19-88 through 3-4-88

POOH w/ prod. equip. TIH, tag fill at 4019'. Perf OH w/ 3 3/4" tornado frac jets at 1SPF, 90° phased, at 3808-32, 3848-51, 3857-60, 3892-3906, 3914-18, 3932-39, 3944-50, 3953-64, 3972-4009. Total 107 holes. Drill fill f/4008 to 4028. Circ. well clean. Set pkr at 3726', acdz open hole w/1500 gall, 15% NEFE HCL, 100 gal, GBW 10#, 100 gal 20# xlink BW w/ 300# GRS, 100gal 10# GBW, repeat steps 1-4 two times, 500 gal acid, flush w/33 bbls 10# BW. RU to swab. Release pkr, TIH w/ WS tag at 4028', no fill, TIH w/ prod. tbg 2 3/8" to 4011'. ND BOP's, NU WH. Run rods, RDPU clean location. Release rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. AkersTITLE Staff Drilling Engr.DATE March 16, 1988

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

MAR 22 1988

RECEIVED

MAR 21 1988

OCD

HOBBS OFFICE