

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
NOTICE OF INTENTION TO TEST WATER SHUT-OFF

Notice must be given to the State Geologist or to the proper Oil and Gas Inspector at least five days before the test. It is desirable that a representative of the Department of the State Geologist witness the water shut-off before drilling into the productive sand whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to sender. Submit this notice in triplicate.

Bartlesville, Oklahoma N. Mex., September 3, 19 35

Mr. E. H. Wells
State Geologist,
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that we intend to test the shut-off of water in Harvey Gulp

Well No. 1 in NW/4 NW/4 of Sec. 19, T. 19N, R. 87E

N. M. P. M., Casper Oil Field Log County,

on September 1 19 35 9 5/8 in. 36 lb. casing was { cemented } in Anhydrite
1200000 }
formation at a depth of 1300 feet on August 29 19 35

525 sacks of O. K. 2 1/2 Paper Mix cement were used.

The method used in placing the cement was as follows: Halliburton

Fluid level will be bailed to a depth of 1300 feet and left undisturbed for at least 12 hours before your inspection.


Adjacent property owners have been notified as follows: Amerada Petroleum Corporation, Gypsy Oil Company, Skelly Oil Company, The Texas Company, Shell Petroleum Corporation.

Additional information:

DUPLICATE

Approved _____ 19____
Except as follows:

Sincerely yours,
Phillips Petroleum Company
Company or Operator.
By Paul J. Hubbell
Position Asst to the Vice President
Send communication regarding well to
Name D. H. Knowlton
Address Bartlesville, Oklahoma



State Geologist or Oil and Gas Inspector.

cc: Earl Griffin
V. M. Spratt

DEPARTMENT OF THE STATE GEOLOGIST
BUREAU OF WATER RESOURCES

REPORT OF INVESTIGATION TO TEST WATER QUALITY

The purpose of this investigation was to determine the quality of water in the... The results of the investigation are as follows...

By order of the State Geologist, *[Signature]*

1910

100-10000

100-10000

100-10000

The following table shows the results of the investigation...

100-10000

100-10000

100-10000

100-10000

100-10000

The following table shows the results of the investigation...

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000

100-10000