

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

C. CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-78

5a. Indicate Type of Lease

State ☒ Fee ☐5. State Oil & Gas Lease No.
B-2052

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)OIL WELL ☒ GAS WELL ☐ OTHER ☐

. Name of Operator

TEXACO Inc.

. Address of Operator

P. O. Box 728, Hobbs, New Mexico 88240

. Location of Well

UNIT LETTER M N 660 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE, SECTION 19 TOWNSHIP 19-S RANGE 37-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

New Mexico 'G' State

9. Well No.

1

10. Field and Pool, or Wildcat
Eunice-Monument Grayburg
San Andres

15. Elevation (Show whether DF, RT, GR, etc.)

3560' (GR)

12. County

Lea

6.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐OTHER ☐PLUG AND ABANDON ☐CHANGE PLANS ☐☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☐CASING TEST AND CEMENT JOBS ☐OTHER Plug Back in Same Zone ☒ALTERING CASING ☐PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIGGED UP. PULL RODS, PUMP AND TUBING.
2. CLEAN OUT.
3. PLUG BACK TOTAL DEPTH FROM 3950 TO 3920' (PBTD) W/CEMENT PLUG.
4. INSTALL PUMPING EQUIPMENT. TEST AND PLACE ON PRODUCTION.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]TITLE Asst Dist MgrDATE 10-2-84

ORIGINAL SIGNED BY HARRY SECTION

APPROVED BY DISTRICT SUPERVISORTITLE DATE OCT - 4 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT - 3 1984

O.C.D.
HOBBS OFFICE