

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-05720

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

East Eumont Unit

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
67

2. Name of Operator
Sirgo Operating, Inc.

9. Pool name or Wildcat
Eumont-Yates-SR-Q

3. Address of Operator
PO Box 3531, Midland, TX 79702

4. Well Location
Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line
Section 28 Township 19S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3592' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| | | | |
|--|---|---|---|
| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| OTHER: <input type="checkbox"/> | | OTHER: <u>Temporarily Abandon</u> <input checked="" type="checkbox"/> | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-8-92 MIRU PU. POH w/rods, pump & tbq. RIH on wireline 5-1/2" CIBP.
Set CIBP @ 3500'. Fill casing to surface with treated fluids.
Move all equipment off location and clean up.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Victor J. Sirgo TITLE Vice-President DATE 7-13-92

TYPE OR PRINT NAME Victor J. Sirgo TELEPHONE NO. 915/685-0878

(This space for SIGNATURE)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUL 15 '92

CONDITIONS OF APPROVAL, IF ANY: