

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05727
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-3998-1
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 11
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER INJECTION WELL

2. Name of Operator
Amerada Hess Corporation

3. Address of Operator
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location
Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line
Section 29 Township 19S Range 37E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: _____ <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1105 (10-21-96 THRU 10-31-96)

TYLER WELL SVC. MIRU. INSTALLED BOP. RELEASED THE PKR. & PULLED THE IPC INJ. TBG. PICKED UP & RAN A LOC-SET RBP ON 123 JTS. OF 2-7/8" TBG. & SET THE RBP @ 3,715'. ATTEMPTED TO RELEASE THE RETRIEVING HEAD FR. THE RBP. WAS UNABLE TO GET OFF THE PLUG. ATTEMPTED TO RELEASE THE SETTING TOOL FR. THE RBP W/NO RESULTS. RELEASED THE RBP. TOH W/TBG. & RBP. TIH W/A NEW RBP ON 123 JTS. OF TBG. & SET THE PLUG @ 3,715'. RELEASED THE SETTING TOOL. STAR TOOL LOADED THE CSG. W/52 BBLs. FW & CIRC. CLEAN. TOH W/TBG. RAN A BAKER FULLBORE PKR. ON 122 JTS. OF TBG. & SET THE PKR. @ 3,696'. PRESS. UP ON THE RBP TO 700#. PRESS. LEAKED OFF IN 30 SECS. TOH W/TBG. & PKR. RAN A RETRIEVING HEAD ON 123 JTS. OF TBG. LATCHED ONTO & RELEASED THE RBP. PULLED THE PLUG TO 3,670' & RESET. RELEASED THE SETTING TOOL & PULLED 1 JT. TBG. LOADED THE (CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 11-01-96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL COPY OF THIS DOCUMENT
TO BE KEPT IN THE OFFICE OF THE
DIRECTOR OF OIL CONSERVATION

NOV 07 1996

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

2023 02 14

2023 02 14
10:00 AM
1000