

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-05781

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
P. O. Box 840, Seminole, Texas 79360-0840

4. Well Location  
Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line  
Section 32 Township 19S Range 37E NMPM Lea County

7. Lease Name or Unit Agreement Name  
North Monument G/SA Unit Blk. 16

8. Well No.  
6

9. Pool name or Wildcat  
Eunice Monument Grayburg San Andres

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Convert to Injection Well.</u> <input checked="" type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
Permit No. WFX716  
Plan to MIRU pulling unit & TOH w/rods. Remove wellhead, install BOP & TOH w/tbg. TIH w/bit & tag PBD at 3925' & attempt to rotate on CIBP. TIH w/RBP set below 3500' & load & test 6-5/8" csg. Install new injection wellhead. Re-install BOP. TIH w/retrieving head, latch onto RBP & TOH. TIH w/GR/CNL. Perforate csg. fr. 3770' - 3784'. Acidize perfs. w/4415 gal. 15% NEFE HCL acid. TIH w/injection eqpt. & begin injection operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Admin. Svc. Coord. DATE 7-17-97  
TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 915 758-6778

(This space for State Use)

APPROVED BY Charles Perri TITLE OIL & GAS INSPECTOR DATE 8-4-97  
CONDITIONS OF APPROVAL, IF ANY: