

NO. OF COPIES RECEIVED	
DISTRIBUTION	
T.A.F.F.	
E.	
G.S.	
NO. OFFICE	
DIATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REWORK OR REEVALUATE TO A DIFFERENT RESERVOIR. USE APPLICATIONS FOR PERMITS AND PROPOSALS.)

OIL WELL  GAS WELL  OTHER

Name of Operator  
Amerada Hess Corporation

Address of Operator  
Drawer D, Monument, New Mexico 88265

Location of Well  
UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM

THE East LINE, SECTION 32 TOWNSHIP 19-S RANGE 37-E NMPM.

15. Elevation (Show whether DF, RT, CR, etc.)  
3587' DF

7. Unit Agreement Name

8. Name of Lease Holder  
D. F. Larsen

9. Well No.  
4

10. Field and Pool, or Well Unit  
Eunice-Monument G/SA

12. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

CRIM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PERMANENTLY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER _____	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull rods, pump & tbg. Check installation of 6-5/8" csg. bowl at 3062'. If parted, dump 20/40 sand in open hole & 100' up into 6-5/8" csg. and run aligning tool thru csg. bowl w/cement retainer on top and attempt to circulate cement to surface. If unable to circ., determine top of cement, perf. 6-5/8" csg. & squeeze so that cement circulates. WOC and drill out cement & test w/1500# press. If OK, clean sand fr. csg. & open hole and perf. Grayburg San Andres zone selectively in open hole and acidize open hole fr. 3795' to 3902' w/6500 gal. 20% HCl NE-FE and 6000 gal. WF-30 in stages. Swab load, re-run prod. equipment and resume prod.

THE COMMISSION MUST BE NOTIFIED  
24 HOURS PRIOR TO COMMENCING WORK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed By E. J. Fisher TITLE Supv. Adm. Ser. DATE 2-16-79

APPROVED BY Jerry Sexton TITLE \_\_\_\_\_ DATE FEB 20 1979

CONDITIONS OF APPROVAL, IF ANY: