

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-05789

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Amerada Hess Corporation

3. Address of Operator
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location
Unit Letter 0 : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line
Section 32 Township 19S Range 37E NMPM LEA County

7. Lease Name or Unit Agreement Name
NORTH MONUMENT G/SA UNIT
BLK. 16

8. Well No.
15

9. Pool name or Wildcat
EUNICE MONUMENT G/SA

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER: CONVERT TO INJECTION WELL.
- PLUG AND ABANDON
- CHANGE PLANS

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- OTHER:
- ALTERING CASING
- PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1615

MIRU PULLING UNIT & REVERSE UNIT. ND WELLHEAD. TOH & LAY DWN. RODS & PUMP. ND WELLHEAD. BU BOP. TOH W/TBG. TIH W/RBP & SET @ +/-500'. INSTALL NEW WELLHEAD EQUIPMENT. TIH W/TBG., & RETRIEVE RBP. TOH W/RBP. TIH W/BIT, D.C.'S & TBG. CLEAN OUT TO TD @ 3,890'. TOH W/BIT. RU SCHLUMBERGER & LOG THE OPENHOLE W/SONIC/CNL/GR TOOLS. TIH W/4" CSG. GUN. PERF. 3,714'-3,773', 2 JSPF, 180 DEG. PHASED HEG CHARGES (59 FEET, 119 TOTAL HOLES). RD SCHLUMBERGER. TIH W/A SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/5,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. AT +/-3,650'. SWAB/FLOW BACK LOAD. TOH W/TBG. & PKR., LAYING DWN. PRODUCTION TBG. P.U. & TIH W/2-3/8" LINED INJ. TBG. W/INJ. PKR. ND BOP. NU INJ. WH ASSEMBLY. RDMO PULLING UNIT. CLEAN LOCATION. OBTAIN SHUT-IN BOTTOMHOLE PRESS. BEFORE INJECTION OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 2-21-96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)
APPROVED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 26 1996