

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER) Recomplete	X

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico

(Place)

September 24, 1956

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the..... **State "H" Lease**

Tidewater Oil Company

(Company or Operator)

Well No. **2** in **K**

(Unit)

NE $\frac{1}{4}$ **SW** $\frac{1}{4}$ of Sec. **32**, T. **19S**, R. **37E**, NMPM., **Monument** Pool

(40-acre Subdivision)

Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Run gamma ray - neutron log to T.D. of 3901'.
Set C.I. B.P. w/ 1 sack cement on top in 7" csg. to plug back from present
producing zone.
Perforate 7" casing opposite likely gas producing zones in the Yates, Seven Rivers,
and Queen formations and recomplete as a gas well.

Approved....., 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION

By.....

Title.....

Tidewater Oil Company

(Company or Operator)

By.....

Position..... **Area Engineer** **W. E. La Roche**

Send Communications regarding well to:

Name..... **H. P. Shackelford**

Address..... **Box 547 Hobbs, New Mexico**