

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1900, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-05801
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name J. H. WILLIAMS "B"
8. Well No. 3
9. Pool name or Wildcat EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3558' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator DRAWER D, MONUMENT, NEW MEXICO 88265
4. Well Location Unit Letter <u>I</u> : <u>1650</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>33</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>CEMENT SQUEEZE & TEST CASING</u> <input checked="" type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
PLAN TO MIRU PULLING UNIT & TOH W/RODS & PUMP. REMOVE WELL HEAD, INSTALL BOP & TOH W/TBG. TIH W/PACKER & EST. INJ. RATE INTO PERFS. FR. 3691' - 3768'. RUN 5-1/2" CEMENT RETAINER SET AT ± 3650' & CEMENT SQUEEZE PERFS. FR. 3691' - 3768' W/150 SKS. CLASS "C" NEAT CEMENT. WOC. TIH W/4-3/4" BIT & DRILL OUT CEMENT RETAINER & CEMENT TO 3790'. PRESS. TEST CASING TO 500# FOR 30 MIN. DRILL OUT CIBP @ 3796' & RUN BIT IN OH TO TD AT 3878'. TOH W/BIT. TIH W/TBG. REMOVE BOP, INSTALL WELL HEAD & TIH W/PUMP & RODS. RDPV & CLEAN LOCATION RESUME PROD. FR. G/SA ZONE OH FR. 3852' - 3878'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE R. L. Wheeler, Jr. TITLE SUPV. ADM. SVC. DATE 12/10/91
TYPE OR PRINT NAME R. L. WHEELER, JR. TELEPHONE NO. 393-2144

(This space for State Use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: