State of New Mexico

Form C-103

submit 3 copies to Appropriate

Energy, Minerals and Natural Resources Department

P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 Santa Fe, New Mexico 87504-2088 Sindicate Type of Lease STATE FEE 6. State Oil / Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: OIL GAS WELL OTHER 2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC. 3. Address of Operator 205 E. Bender, HOBBS, NM 88240 4. Well Location Unit Letter E : 2088 Feet From The NORTH Line and 660 Feet From The WEST Line Section 6 Township 20S Range 37E NMPM LEA COUNTY	District Office		·	Revised 1-1-89
DISTRICT P.OS. DAY DAY OF COMMENT OF CONTROL OF COMMENT OF	DISTRICT I O	IL CONSERVATI	ON DIVISION	WELL API NO.
SATISTECT ID. Artesia, NM 89210 STATE FE STATE FE		P.O. Box 20	88	30-025-05960
STATE OF PEED STATE OF A STATE OF PEED STATE OF A STA		Santa Fe, New Mexic	co 87504-2088	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 SUNDEY, NOTICES AND REPORTS ON WELL	•	•		STATE ☐ FEE ☒
COO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO GEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (PORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: MEL	1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil / Gas Lease No.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: OL. GAS 2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC. 3. Address of Operator TEXACO EXPLORATION & PRODUCTION INC. 3. Address of Operator 1. Address of Operator TEXACO EXPLORATION & PRODUCTION INC. 3. Address of Operator 1. Type of Well: O. T. C. GAS 4. Well Location Until Letter E. 2088 Feet From The NORTH Line and .660 Feet From The WEST Line Section 6 Township 29S Range 37E NMPM LEA COUNTY 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEMPORABILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT CHANGE TO A LITERING CASING TOTHER: 1. CASING TEST AND CEMENT JOB PLUG AND ABANDONNENT CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT CHANGE PLANS COMMENCE PRODUCE TO A LITERING CASING COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT CHANGE AND A LITERING CASING COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT COMMENCE TO A LITERING CASING COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT COMMENCE TO A LITERING CASING COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT COMMENCE TO A LITERING CASING COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT COMMENCE TO A LITERING CASING COMMENCE DRILLING OPERATION PLUG AND ABANDONNENT COMMENCE TO A LITERING CASING CO		ES AND REPORTS ON WE	LL	
FORM C-101) FOR SUCH PROPOSALS PHILLIPS, JR.		7. Lease Name or Unit Agreement Name		
WELL WILL OTHER 2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC. 3. Address of Operator 205 E. Bender, HOBBS, NM 88240 5. Pool Name of Wildoar SUMONT; VAITES-PRYRS-QUEEN (PRO GAS) 4. Well Lacation Unit Letter E : 2088 Feet From The NORTH Line and 660 Foet From The WEST Line Section 6 Township. 205 Range 37E NMPM LEA. COUNTY 10. Bevarion (Show whether DF, RKB, RT.GR, etc.) 3577 DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CASING CASING CASING CERTIFICATION FROM THE PROPERTY OF THE PRO			PERMIT	PHILLIPS, J.R.
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC. 3. Address of Operator 205 E. Bender, HOBBS, NM 88240 4. Well Location Unit Letter E. 2088 Feet From The NORTH Line and 660 Feet From The WEST Line Section 6 Township 20S Range 37E NMPM LEA. COUNTY Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PREPROM REMEDIAL WORK PULG AND ABANDON CHANGE PLANS COMMENCE OF RUBBER AND CHANGE PLANS COMMENT JOB COME	i. Type of well.	OTHER		
3. Address of Operator 205 E. Bender, HOBBS, NM 68240 4. Well Location Unit Letter E: 2088 Feet From The NORTH Line and 680 Feet From The WEST Line Section 6 Township 20S Range 37E NMPM LEA COUNTY	2. Name of Operator			8. Well No.
4. Well Location Unit Letter E: 2088 Feet From The NORTH Line and 660 Feet From The WEST Line Section 6 Township 20S Range 37E NMPM LEA COUNTY 10. Elevation Ishow whether DF, RKB, RT,GR, etc.) 3577 DF	2. Address of Operator			9. Pool Name or Wildcat
Section 6 Township 20S Range 37E NMPM LEA COUNTY 10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3577 DF	4. Well Location	OBB0, 14147 002-40		EUMONT; YATES-7-RVRS-QUEEN (PRO GAS)
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3577 DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK		88 Feet From The NOF	RTH Line and 660	Feet From The WEST Line
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: POULL OR ALTER CASING OTHER: REQUEST TA APPROVAL OTHER: REQUEST TA APPROVAL OTHER: REQUEST TO SOPPOSE OF COMPLETE OF THE PROPERTY	Section 6 To	ownship 20S	Range 37E NM	MPMLEA_COUNTY
NOTICE OF INTENTION TO: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF COMPLETE OF THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL 3 - THE PROPOSED OF CASING TEST AND CEMENT JOB OT	11	O. Elevation (Show whether DF, F	RKB, RT,GR, etc.) 3577' DF	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL OTHER: REQUEST TA APPROVAL OTHER: REQUEST TA APPROVAL OTHER: REQUEST TO APPROVAL OTHER: REQ	11. Check Appro	opriate Box to Indicate N	ature of Notice, Report	t, or Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: REQUEST TA APPROVAL OTHER: REQUEST TA APPROVAL OTHER: REQUEST TA APPROVAL OTHER: REQUEST TO APPROVAL OTHER: REQ	NOTICE OF INTENTION	TO:	St	JBSEQUENT REPORT OF:
TEMPORABILLY ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPERATION CASING TEST AND CEMENT JOB COMMENT CASING TEST AND CEMENT JOB COMMENT JOB		_		
PULL OR ALTER CASING COTHER: REQUEST TA APPROVAL 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent detes, including estimated date of starting any proposed work) SEE RULE 1103. 9-17-98: MIRU. OPEN WELL UP. PUMP STUCK BACK OFF RODS & LD 56 7/8" RODS, & 78 3/4" RODS. PMP WATER DOWN CSG. KILL WELL. UNFLANGE WELL. INSTL BOP, PULL TBG & TOH. 9-18-98: PUMP 15 BBLS DN CSG. KILL WELL, PU CIBP & RUN TBG IN HLE. SET PLUG @ 2945" FR SURF, MADE 2 CMT RUNS W/SANDLINE. DUMP 35 CMT ON TOP OF PLUG. THE WYTBG OPEN ENDED DN TO 2935". CIRC W/65 BBLS PKR FLUIC. LD TBG. TEST CSG TO 500 PSI FOR 30 MIN. HELD OK. REM BOP. FLANGE WELL ON. (CHART FOR NMOCD. ORIGINAL CHART ATTACHED & COPY OF CHART ON BACK) That's Approval of the information about 4 and and cognitive to the information about 4 and bated. SIGNATURE TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405	TEM ONW NEWEDIAE WORK	_		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 9-17-98: MIRU. OPEN WELL UP. PUMP STUCK. BACK OFF RODS & LD 56 7/8" RODS, & 78 3/4" RODS. PMP WATER DOWN CSG. KILL WELL. UNFLANGE WELL. INST. BOP. PULL TBG & TOH. 9-18-98: PUMP 15 BBLS DN CSG. KILL WELL. PU CIBP & RUN TBG IN HLE. SET PLUG @ 2945 FR SURF. MADE 2 CMT RUNS W/SANDLINE. DUMP 35 CMT ON TOP OF PLUG. TIH W/TBG OPEN ENDED DN TO 2935. CIRC W/65 BBLS PKR FLUIC. LD TBG. TEST CSG TO 500 PSI FOR 30 MIN. HELD OK REM BOP. FLANGE WELL ON. (CHART FOR NMOCD. ORIGINAL CHART ATTACHED & COPY OF CHART ON BACK) Thereby centry that the information about 1 the and complete to the recoverable and better SIGNATURE TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405	TEMPORATION D	ANGE FLANS		<u> </u>
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 9-17-98: MIRU. OPEN WELL UP, PUMP STUCK, BACK OFF RODS & LD 56 7/8" RODS, & 78 3/4" RODS. PMP WATER DOWN CSG. KILL WELL. UNFLANGE WELL, INSTL BOP, PULL TBG & TOH. 9-18-98: PUMP 15 BBLS DN CSG. KILL WELL. PU CIBP & RUN TBG IN HLE. SET PLUG @ 2945' FR SURF. MADE 2 CMT RUNS W/SANDLINE. DUMP 35 CMT ON TOP OF PLUG. THE WYTEG OPEN ENDED DN TO 2935' CIRC W/65 BBLS PKR FLUID. LD TBG. TEST CSG TO 500 PSI FOR 30 MIN. HELD OK REM BOP. FLANGE WELL ON. (CHART FOR NMOCD. ORIGINAL CHART ATTACHED & COPY OF CHART ON BACK) These yearsty that the information above for the and complete to the starting and balled. SIGNATURE SIGNATURE J. Denise Leake Telephone No. 397-0405			ł	_
Any proposed work) SEE RULE 1103. 9-17-98: MIRU. OPEN WELL UP, PUMP STUCK BACK OFF RODS & LD 56 7/8" RODS, & 78 3/4" RODS. PMP WATER DOWN CSG. KILL WELL. UNFLANGE WELL. INST. BOP. PULL TBG & TOH. 9-18-98: PUMP 15 BBLS DN CSG. KILL WELL. PU CIBP & RUN TBG IN HLE. SET PLUG @ 2945' FR SURF. MADE 2 CMT RUNS W/SANDLINE. DUMP 35' CMT ON TOP OF PLUG. TH W/TBG OPEN ENDED DN TO 2935'. CIRC W/65 BBLS PKR FLUID. LD TBG. TEST CSG TO 500 PSI FOR 30 MIN. HELD OK. REM BOP. FLANGE WELL ON. (CHART FOR NMOCD. ORIGINAL CHART ATTACHED & COPY OF CHART ON BACK) That's Approval 31' The SAPEN VALUE of the information above the drue and cognitive to the province of a round belief. SIGNATURE Of the street of the same transfer of the province of the same transfer of the same tr	OTHER:	U	OTHER:	RECOEST TA APPROVAL
Thereby certify that the information above is due and complete to the barroll my knowledge and belief. SIGNATURE SIGNATURE SIGNATURE J. Denise Leake Type OR PRINT NAME J. Denise Leake Telephone No. 397-0405	UNFLANGE WELL. INSTL BOP. PULL TBG 6 9-18-98: PUMP 15 BBLS DN CSG. KILL WEI DUMP 35' CMT ON TOP OF PLUG. TIH W/T	& TOH. LL. PU CIBP & RUN TBG IN HI BG OPEN ENDED DN TO 293 DN. (CHART FOR NMOCD. C	.E. SET PLUG @ 2945' FR : 5'. CIRC W/65 BBLS PKR F ORIGINAL CHART ATTACH	SURF. MADE 2 CMT RUNS W/SANDLINE. LUID. LD TBG. TEST CSG TO 500 PSI FOR 30 ED & COPY OF CHART ON BACK)
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405	1 - 1/20	the bay of my knowledge and belief.		·
This was to Constitute			The state of the s	
(This areas for Chara (Inc.)	TYPE OR PRINT NAME J. Der	· · · · · · · · · · · · · · · · · · ·		Telephone No. 397-0405
	(This snare for State Use)	***		

DeSoto/Nichols 12-93 ver 1.0

10 C

CONDITIONS OF APPROVAL, IF ANY:

