

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.

LC-031621A

6. If Indian, Allottee or Tribe Name

**SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.

MAY 12 P 3:16

SUBMIT IN TRIPLICATE

BUREAU OF LAND MGMT.  
BOBBS, NEW MEXICO

1. Type of Well

Oil Well  Gas Well  Other

2. Name of Operator

Doyle Hartman

3. Address and Telephone No.

P.O. Box 10426, Midland, TX 79702-7426

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 1980' FWL (Unit F), Section 7, T-20-S, R-37-E

7. If Unit or CA, Agreement Designation

8. Well Name and No.

H.M. Britt No. 1

9. API Well No.

30-025-05972

10. Field and Pool, or Exploratory Area

Eunice Monument

11. County or Parish, State

Lea County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other <u>Test Casing / Temporarily Abandon</u>
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Move in, rig up and pull tubing and packer.
2. Set retainer at +/- 3550'.
3. Load casing with non-corrosive fluid and test casing for integrity. Repair or P&A if necessary.
4. If the casing integrity is good then well will be temporarily abandoned in order to evaluate recompletion potential.

APPROVED  
PETER W. CHESTER  
MAY 24 1999  
BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA

14. I hereby certify that the foregoing is true and correct

Signed Doyle Hartman Title Engineer Date 05/03/99

(This space for Federal or State office use)

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GWW

\*See Instruction on Reverse Side