MOLTURE	Form C-103 Supersedes Old
NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
	5a. Indicate Type of Lease
-)FFICE	State Fee X
OR	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR TO SOME CHAPPELICATION FOR PERMIT - " FORM C-1011 FOR SIGH PROPOSALS.)	
I WELL X GAS WELL OTHER. Plug & Abandon	7. Unit Agreement Name
Atlantic Richfield Company	8. Farm or Lease Name
3. Address of Operator	Bertha J. Barber 9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240	17
UNIT LETTER I 2310 FEET FROM THE South LINE AND 495	10. Field and Pool, or Wildcat
THE East LINE, SECTION 7 TOWNSHIP 20S RANGE 37E	NMPM. (())
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3551' GR	Lea
Check Appropriate Box To Indicate Nature of Notice, Repor	t or Other Data
	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT X
PULL OR ALTER CASING LOST AND CEMENT JOB	Mon. Blinebry zone only
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details, work) SEE RULE 1103.	
work) SEE RULE 1103.	including estimated dave of starting any proposed
On 3/19/75 installed BOP. Ran 6-1/8" bit & scraper to 5347'. In community co	40'. Squeeze perfs 5542-5557
id. I hereby certify that the information above is true and implicate to to	A C C C C C C C C C C C C C C C C C C C
1/1 2	
Dist. Drlg. Supv.	4/15/75