

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Farm or Lease Name State A2 RA/A
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240		9. Well No. 11-Y
4. Location of Well UNIT LETTER <u>C</u> <u>810</u> FEET FROM THE <u>North</u> LINE AND <u>2030</u> FEET FROM THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Wildcat Yates
15. Elevation (Show whether DF, RT, GR, etc.) 3639' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in service unit 9-7-82. Ran tubing and tagged plug at 3310'. Loaded hole and established injection rate. Ran cement retainer and set at 3120'. Squeezed perfs 3172'-3224' with 184 sacks class C neat. Reversed out 76 sacks. Displaced hole with 220 barrels fresh water. WOC.

O+4-NMOCD, H 1-HOU 1=DMF 1-W. Stafford, HOU

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Assist. Admin. Analyst DATE 9-17-82

ORIGINAL SIGNED BY
APPROVED BY JERRY SEXTON TITLE _____ DATE SEP 23 1982
CONDITIONS OF APPROVAL _____