

JPL CATE NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS NOTICES

1954 APR 23 PM 3:45

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be ti

urned to the sender on whi agent, of the plan submittee nal instructions in the Rule	s and Regulat	Indicate Nature of Notice by	y Checking Below			
otice of Intention		NOTICE OF INTENTION TO		Notice of Intention to Drill Deeper		
CHANGE PLANS	X	TEMPORARILY ABANDON WELL NOTICE OF INTENTION		Notice of Intention to Set Liner		
PLUG WELL OTICE OF INTENTION		TO PLUG BACK NOTICE OF INTENTION TO ACIDIZE		Notice of Intention to Shoot (Nitro)		
OTICE OF INTENTION		Notice of Intention (Other)		Notice of Intention (Other)		
GUN PERFORATE IL CONSERVATION CO ANTA FE, NEW MEXICO	MMISSION	Midland, Texas		April 26), 195/	t
			. н. і). McKniley		
Following is a Notice of Intention to do certain work as described. The Texas Company (Company or Operator) NE 1/4 SE 1/4 of Sec. 5, T. 19-3, R. (40-acre Subdivision)						
Ine reads comp	mpany or Opera	tor) 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	_R	Bowers		Poo
Form C-10	FI (FOLL) 2 submi	ULL DETAILS OF PROPO OW INSTRUCTIONS IN THE tted on February 1 sire to recomplete	SED PLAN OF	F WORK REGULATIONS)	rmi ssi	.on to
Form C-10 plug well. We a gas well in Set a dri of Hydromite of with 2 bullets	FOLLO 2 subminow de the folunte folunte folunte for the format	ULL DETAILS OF PROPO OW INSTRUCTIONS IN THE tted on February 1 sire to recomplete lowing manner: bridging plug at 2 f plug. Perforate ot, and wash perfo ion with 6000 gall	SED PLAN OF RULES AND F. 1954, well in 2985 feet	F WORK (EGULATIONS) requested pethe Yates for and spot eight from 2818 th 500 gallo	rmissi rmatio ht gal to 286	on to n as lons 8 feet acid.
Form C-10 plug well. We a gas well in Set a dri of Hydromite o	FOLLO 2 subminow de the folunte folunte folunte for the format	ULL DETAILS OF PROPO OW INSTRUCTIONS IN THE tted on February 1 sire to recomplete lowing manner: bridging plug at 2 f plug. Perforate ot, and wash perfo ion with 6000 gall	SED PLAN OF RULES AND F. 1954, well in 2985 feet	F WORK (EGULATIONS) requested pethe Yates for and spot eight from 2818 th 500 gallo	rmissi rmatio ht gal to 286	on to n as lons 8 feet acid.
Form C-10 plug well. We a gas well in Set a dri of Hydromite of with 2 bullets Also, fracture pounds of sand	FI (FOLL) 2 subminow de the foluntop of per format l, if ne	ULL DETAILS OF PROPO DW INSTRUCTIONS IN THE tted on February 1 sire to recomplete lowing manner: bridging plug at 2 f plug. Perforate ot, and wash perfo ion with 6000 gall cessary.	SED PLAN OF RULES AND F. 1954, well in 2985 feet Train willons of Cr.	requested pethe Yates for and spot eig from 2818 th 500 galloude oil carr	rmissi rmation ht gal to 286 ms of ying	lons feet acid.
Form C-10 plug well. We a gas well in Set a dri of Hydromite of with 2 bullets Also, fracture pounds of sand Approved	FI (FOLL) 2 subminow de the foluntop of per format l, if ne	ULL DETAILS OF PROPO OW INSTRUCTIONS IN THE tted on February I sire to recomplete lowing manner: bridging plug at 2 f plug. Perforate ot, and wash perfo ion with 6000 gall cessary.	SED PLAN OF RULES AND F. 1954, well in 2985 feet a 7" casin oration willons of cr. The Texas Sensition Asst	requested pethe Yates for and spot eig from 2818 th 500 galloude oil carr	rmissi rmatic ht gal to 286 ns of ying	lons feet acid.