STATE OF NEW MEXICO MERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION MD. 67 COPIER ACCCIVED DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501 1116 5a. Indicate Type of Lease U.3.0.3 State X LAHO OFFICE 5, State Oil & Gas Lease No. OPERATOR A-1212 SUNDRY NOTICES AND REPORTS ON WELLS FOR MAINTENEST TO CRILL ON TO GEEPLY OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name WELL Injection OTHER-Nume of Operator 8. Farm or Lease Name Amoco Production Company South Hobbs (GSA) Unit . Address of Operator 9. Well No. 50 P. O. Box 68, Hobbs, NM 88240

Form 0-103

10, Field and Pool, or Wildcat

Hobbs GSA

12. County

Revised 10-1

Lea 3628' DF Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: POLE OF ALTER CASING CASING TEST AND CEMENT JOB Convert to injection Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103. Moved in service unit 5-18-81. Tagged bridge plug at 4120'. Drilled bridge plug. Perforated 3988'-92', 4008'-14', 4092'-98', 4103'-06', 4150'-72', 4191'-95', 4202'-10', 4233-40' with 2 SPF. Packer set at 3890'. Pumped 6000 gallons 15%

NE HCL acid tagged with radioactive Iodine 131. Flushed with brine water.

Swab load and place well on injection.

1-Hou

1-GPM

South

15. Elevation (Show whether DF, RT, GR, etc.)

19-S

ify that the information above is true and complete to the best of my knowledge and belief. Admin. Analyst 6-30-81 Orig. Signed by Jerry Section

1-Susp

0+4-NMOCD, H

. Location of Well

UNIT LETTER