TIONS

REPORT ON BEGINNING DRILLING OPERA-

## 'ATION COMMISSION



Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission. Indicate nature of report by checking below.

REPORT ON REPAIRING WELL

REPORT ON PULLING OR OTHERWISE

REPORT ON RESULT OF SHOOTING OR CHEM- ICAL TREATMENT OF WELL		N PULLING OR OTHERWIS RING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT O	N DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	*		
	May 27, 1948 Date	Labbook,	
OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO Gentlemen:	Succ		•
Following is a report on the work done and the resul			
S. R. Cone		Well No	in the
Company or Operator  OR / A ST / A ST / A Of Sec. 9	Lease , T <b>19</b>	, R <u>38</u>	имрм
Field,		, 1	
The dates of this work were as follows:			
Notice of intention to do the work was (	-	102 on May 6.	19 48
	obtained. (Cross out in	correct words.)	
DETAILED ACCOUNT OF Commented 20 sax at 4065 mfills with 50 sax then filled with m mud and coment well marker in twell.	WORK DONE AND RI ed hole with heav ed and set 20 sax	y mud and cemented at plug at 1850' filled	with
Cemented 20 sax at 4065 -fills with 50 sax then filled with m mud and cement well marker in	WORK DONE AND RI ed hole with heav ed and set 20 sax	y mud and cemented at plug at 1850' filled	with
Cemented 20 sax at 4065 - fills with 50 sax then filled with m mud and cement well marker in twell.	work done and ried hole with heavy and and set 20 sex top of 8 5/8" sur:	y mud and cemented at plug at 1850' filled	with 't in
Cemented 20 sax at 4065 — fills with 50 sax then filled with m mud and cement well marker in twell.  Witnessed by W. H. Bodson	work DONE AND RI  ad hole with heavy  ad and set 20 sax  top of 8 5/8" sur:  Hobbs Pipe  Com	y mud and cemented at plug at 1850' filled face pipe which is left Supply Company, Hobbupany or affirm that the information	with t in a. <u>New Meri</u> Title
Cemented 20 sax at 4065'-fills with 50 sax then filled with me much and cement well marker in well.  Witnessed by W. H. Dodson Name	WORK DONE AND RI  ad hole with heavy  ad and set 20 sax  top of 8 5/8" sur:  Hobbs Pipe  Com  I hereby swear is true and corr	y mud and cemented at plug at 1850' filled face pipe which is left Supply Company, Hobbupany or affirm that the information	with t in a. <u>New Meri</u> Title
Cemented 20 sax at 4065 — fills with 50 sax then filled with me mand and cement well marker in well.  Witnessed by H. H. Rodson Name  Subscribed and sworn before me this 2713	work done and rived hole with heavy and and set 20 sax top of 8 5/8" sur:  Hobbs Pipe Com I hereby swear is true and corr	y mud and cemented at plug at 1850' filled face pipe which is left Supply Company, Hobbupany or affirm that the information	vith t in 
Cemented 20 sax at 4065 — fills with 50 sax then filled with me mand and cement well marker in well.  Witnessed by H. H. Bodson Name  Subscribed and sworn before me this	WORK DONE AND RI  od hole with heavy  od and set 20 sax  top of 8 5/8" sur:  Libbs Pipe  Com  I hereby swear is true and corr  AS Name  Position	y mud and cemented at plug at 1850' filled face pipe which is left Supply Company, Hobbapany or affirm that the information ect.	with t in a. <u>New Mexi</u>
Cemented 20 sax at 4065'—fills with 50 sax then filled with me mud and cement well marker in well.  Witnessed by H. Bodson Name  Subscribed and sworn before me this 2713' day of 19.	Hobbs Pipe  Com  I hereby swear is true and corr  Name  Position  Representing	y mud and cemented at plug at 1850' filled face pipe which is lef  & Supply Company, Hobb apany  or affirm that the information ect.	with t in Title given above
Cemented 20 sax at 4065'-fills with 50 sax then filled with me much and cement well marker in well.  Witnessed by W. H. Bodson Name  Subscribed and sworn before me this 27th day of 19	Hobbs Pipe  Com  I hereby swear is true and corr  Name  Position  Representing	y mud and cemented at plug at 1850' filled face pipe which is lef  & Supply Company, Hobb  apany  or affirm that the information ect.  Company or Operator	with t in Title given above

Markeyer