STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| we. or tories hectives | |
|------------------------|--|
| MOLTURINTZIO | |
| SANTA PE | |
| FILE | |
| U.1.0.1. | |
| LAND OFFICE | |
| OPERATOR ' | |

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

OIL CONSERVATION DIVISION

• 7 E

.... FEB 2

| DISTRIBUTION | | . DOX 2088 | Form C-103 Revised 10-1- |
|---|--|---|--|
| rice | SANTA FE, 1 | NEW MEXICO 87501 | |
| U.1.0.1. | · | | Sa. Indicate Type of Letse |
| LAND OFFICE | | | State X Fro |
| OPERATOR ' | | | 5. State Off 6 Gas Lease No. A-1212 |
| SUNDR | Y NOTICES AND REPORTS | ON WELLS | |
| USE "APPLICATI | ON FOR PERMIT -" (FORM C-161) FO | TH SUCH PROPOSALS,) | |
| OIL X SAS WELL | OTHER- | | 7, Unit Agreement Name |
| 2. Name of Operator | DANIV | | 8. Farm or Lease Name |
| AMOCO PRODUCTION COMPANY 1. Address of Operator | | South Hobbs (GSA) Un | |
| P. O. Box 68, Hobbs, | NM 88240 | | 9. Well No. |
| 4. Location of well | | 10. Field and Pool, or Wildcal | |
| UNIT LETTER B 6 | 60 North | 1 · 1980 | 11-1-1 000 |
| East | 9 N TOWNSHIP | 19-S 38-E | |
| THE LINE, SECTIO | N TOWNSHIP | RANGE NM | PM. (|
| | 15. Elevation (Show wh | ether DF, RT, GR, etc.) | 12. County |
| | | 3605' DF | Lea |
| Check A | Appropriate Box To Indica | te Nature of Notice, Report or (| Other Data |
| NOTICE OF IN | TENTION TO: | • | NT REPORT OF: |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | |
| TEMPORARILY ABANDON | | COMMENCE DRILLING OPHS. | ALTERING CASING PLUG AND ABANDONMENT |
| PULL OR ALTER CASING | CHANGE PLANS | CASING TEST AND CEMENT JOB | |
| | • | OTHER CONVERT to In. | jector |
| OTKER | | | . – |
| 17. Describe Proposed or Completed Operark) SEE RULE 1103. | erations (Clearly state all pertinen | t details, and give pertinent dates, include | ng estimated date of starting any propose |
| Moved in service uniopen hole interval 3 out cement, calseal, tubing landing at 36 to 4278' and pressurdump bailer, and pluto 1000 psi and OK. 4191'-97', 4200'-08' NE HCL and additives 50 psi. ISIP 190 ps 3996'. Displaced camboved out service un 0+4-NMOCD, H 1-HOUR 1-Petro Lewis | t 12-6-83. Plugged by 993'-4106' with 280 so sand and formation to 59'. Cemented with 10 gged back with sand a Perforated 4122'-43', 4209'-11' and 4215'. Flushed and air 2 i with 5 min SIP Vac. sing with packer fluit 12-21-83. No furt | pack with sand and calseal cacks class C and reversed to 4280'. Ran 4-1/2" lines 00 sacks class C and circulon psi. Bled down to 300 and calseal to 4265'. Pres 4148'-51', 4165'-71', 42-21' with 4 JSPF. Acidize BPM with max. pressure 750 Ran packer and tubing with the control of the report until injection 1-F. J. Nash, HOU Rm. 4 | to 4106'. Squeezed out 63 sacks. Drilled r set at 4280 with plated. Drilled out psi. Logged, ran saure tested casing 177'-80', 4182'-87', ed with 3000 gals 15% psi and min. pressure ith packer set at r at 500 psi and 0K. In commences. |
| A.T. N | | | |
| TICHEO TOUR | Jema TITLE_ | Assist. Admin. Analyst | 1-31-84 |
| | | | |