

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.	30-025-07674
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
South Hobbs (GB/SA) Unit	
8. Well No.	94
9. Pool name or Wildcat	Hobbs Grayburg/San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3588.5' GL	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator	Altura Energy, Ltd.
3. Address of Operator	P.O. Box 4294 Houston, Texas 79210-4294
4. Well Location	Unit Letter N : 330 Feet From The South Line and 2310 Feet From The West Line
Section 10	Township 19-South Range 38-East NMPM Lea, NM County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3588.5' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11/18/97 OCD NOTIFIED, P&A INTENT, RIH W/2-3/8" WORKSTRING, TAG CIBP @3946'.
- 11/18/97 PUMP MLF 32V.
- 11/19/97 OCD NOTIFIED, CAP CIBP W/35 SXS (C) CMT 3946'-3808'.
- 11/19/97 PERF 4 HOLES @ 2800', 8-5/8" PKR @ 2552', PSI TO 1200# HOLDING, OCD NOTIFIED SPOT 35 SXS "C" IN 8-5/8" 2860'-2722'.
- 11/20/97 SET PKR 1500', TAG TOC 2720', OCD NOTIFIED, PERF 1735', PSI 1400#, NOTIFIED OCD UNABLE TO SQ., SPOT 50 SXS "C" CMT IN 8-5/8" FROM 1803'-1606'.
- 11/21/97 TAG CMT @ 1612', OCD NOTIFIED, PUMP 80 BBLS MLF, SPOT 53 SXS "C" CMT FILL 8-5/8" CSG FROM 168' TO SURFACE & CAP.
- 11/21/97 CUT OFF WELL HEAD, INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James L. Bagley TITLE P&A Supervisor DATE 11/21/97  
TYPE OR PRINT NAME James L. Bagley TELEPHONE NO. 915-530-0907

(This space for State Use)

APPROVED BY Johnny Robinson TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_