

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
OG-4067

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texaco Inc.	8. Farm or Lease Name New Mexico "CV" State
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>20S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat Delaware
15. Elevation (Show whether DF, RT, GR, etc.) 3661' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU PU. ND Tree. Install BOP. Load hole with 9.5 PPG mud.
- 2) Spot 25 sx Class "H" cement plug from 5600' to 5262'. SION.
- 3) Tag plug. Pull up laying down tubing to 3800'.
- 4) Spot 25 sx Class "H" cement plug from 3800' to 3462'.
- 5) Spot 25 sx Class "H" cement plug from 1900' to 1562'.
- 6) Spot 10 sx Class "H" cement plug from 135' to surface.
- 7) Install abandonment marker. RDPU. Clean location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE COMMENCING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ja Head TITLE Hobbs Area Superintendent DATE June 8, 1987

APPROVED BY Paul Kautz TITLE Geologist DATE JUN 11 1987

CONDITIONS OF APPROVAL, IF ANY:

397-3571

RECEIVED
JUN 10 1987
OCD
HOBS OFFICE

1987 JUN 10 10 10 AM
HOBS OFFICE