

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

~~SUNDRY NOTICES OF INTENTION~~ REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

**MAY 14 11 16 AM '68**

5. LEASE DESIGNATION AND SERIAL NO.

**NA 020543**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

**Government 'W' Can**

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

**Wildcat**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

**All of sections 19 & 30  
Twp. 20E - Rge 24E**

12. COUNTY OR PARISH

**Lee**

13. STATE

**New Mexico**

1. OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR  
**Cities Service Oil Company**

3. ADDRESS OF OPERATOR  
**P. O. Box 69 - Hobbs, New Mexico**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface

**660' FSL & 1983.9' FUL Sec. 19-20E-24E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**3675' DF**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**The above well was spudded on 4-22-68 and drilled to TD of 1545'. In attempting to set 20' casing the casing parted. The hole was junked and we propose to plug and abandon in the following manner:**

- 1. 50' plug above baffle collar at 1468' in 20' fish (approx. 50 sack).**
- 2. 100' plug one-half in and one-half out of top of 20' fish at 333' (approx. 175 sack).**
- 3. 100' plug in 26" open hole 300' to 400' (approx. 250 sack).**
- 4. 20' plug in top of 30' conductor pipe (approx. 50 sack).**
- 5. Fill collar. Erect 4' dry hole marker extending 4' above ground level to indicate P & A location.**

18. I hereby certify that the foregoing is true and correct

SIGNED

**ORIGINAL SIGNED  
G. D. ROBERTSON**

TITLE

**District Clerk**

DATE

**May 9, 1968**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

**APPROVED**

DATE

**MAY 9 1968**

**A. R. BROWN  
DISTRICT ENGINEER**

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

MAY 14 11 18 AM '68

MOBES OFFICE O.C.C.