

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
A-1375

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT..." (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Moran Exploration, Inc. 3. Address of Operator 400 Wilco Bldg., Midland, Texas 79701 4. Location of Well UNIT LETTER <u>I</u> <u>660'</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>19</u> TOWNSHIP <u>20S</u> RANGE <u>36-E</u> NMPM.	7. Unit Agreement Name 8. Farm or Lease Name Osudo State 9. Well No. 1 10. Field and Pool, or Wildcat N. Osudo Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3634' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spotted 15 sx cement 11,070 - 10,867'.
- Ran tubing. Circulated casing with mud laden fluid.
- Spotted 35 sx cement plug @ 11,070'.
- Spotted 20 sxs cement in 4-1/2" casing 6448 - 6231' (217' fill).
- Shot off casing @ 5486'.
- Set 85 sx cement plug 6076 - 5280' in 4-1/2" casing and which also covers 8-5/8" shoe @5249
- Spotted 50 sx cement plug 2000 - 1828'.
- Spotted 50 sx cement plug 805 - 667'.
- Spotted 75 sx cement plug 400 - 280'.
- Set 10 sx cement plug @ surface and installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jessie Q. Sorenson TITLE Division Production Supt. DATE 8-27-81.
APPROVED BY Ronald Cuthbert TITLE OIL & GAS INSPECTOR DATE 8-27-81
CONDITIONS OF APPROVAL, IF ANY: