

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-23632
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name J.R Phillips "A"
8. Well No. 9
9. Pool name or Wildcat Eumont Yates SRQ

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
ARCO Permian

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

4. Well Location
Unit Letter M : 800 Feet From The S Line and 660 Feet From The SW Line
Section 31 Township 19S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3586' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	OTHER: _____ <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01/26/99: POH w/tbg & tools. Set CIBP @ 5069'. Spot 25 sxs cmt on top of CIBP. Displace hole w/9.5# 54 viscosity mud. Spot 25 sxs smt plug @ 3645-3545'. Spot 25 sxs plug @ 1125-1025'. Spot 25 sxs cmt plug @ 610-510'. Spot 15 sxs cmt plug @ 15' to surf. NMOCD notified and witnessed by Mr. Buddy Hill.

01/27/99: RDSU. Cut off wellhead. Install permanent marker. Dig out & cut off safety anchors. Well P&A'd 01/27/00.

ok
BD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 01/27/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

AUG 16 2000

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: