

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

| | |
|---|--|
| API NO. (assigned by OCD on New Wells) 30-025-25395 | |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> | |
| 6. State Oil & Gas Lease No. N/A | |
| 7. Lease Name or Unit Agreement Name MONUMENT ABO | |
| 8. Well No. 1 | |
| 9. Pool name or Wildcat NORTH MONUMENT ABO POOL | |
| 10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3741' GL | |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON

4. Well Location
Unit Letter G : 1650 Feet From The NORTH Line and 1700 Feet From The EAST Line
Section 14 Township 19S Range 36E NMPM LEA County

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| | | | |
|--|---|---|---|
| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTER CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABAN. <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | | CASING TEST AND CMT JOB <input type="checkbox"/> | |
| OTHER: _____ <input type="checkbox"/> | | OTHER: <u>ADD PAY & ACID FRAC</u> <input checked="" type="checkbox"/> | |

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK STARTED 09/12/94. MIRU PU, ND WH, NU BOP. RUN GR F/7440'-6600'. PERF F/7214'-7272'. DUMP 20' OF CMT ON TOP OF CIBP AT 7400'. LOAD CSG W/85 BBLs 2% KCL. ACID FRAC PERFS W/12,000 GALS 20% HCL FLUSHED W/2% KCL. FLUSH, SWAB. PERF F/7052'-7124'. ACDZ NEW PERFS W/15% HCL AND 20,000 GALS GELLED HCL. SWAB. SPOT 500 GALS HCL NEFE F/7010'-6510'. PERF F/6946'-6982'. SWAB. ACDZ W/10,000 GALS 20% HCL. SWAB. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 09/26/94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Wendi Kingston* TITLE TECH. ASSISTANT DATE: 10/25/94

TYPE OR PRINT NAME WENDI KINGSTON TELEPHONE NO. (915)687-7826

APPROVED BY DELEON FERRER TITLE _____ DATE OCT 27 1994

CONDITIONS OF APPROVAL, IF ANY: _____