

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26168
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	W. A. Weir "B"
8. Well No.	3
9. Pool name or Wildcat	Eumont Yates 7RQ

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Amerada Hess Corporation

3. Address of Operator
P. O. Box 840, Seminole, Texas 79360-0840

4. Well Location
Unit Letter B : 660 Feet From The North Line and 1980 Feet From The East Line
Section 26 Township 19S Range 36E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3660.1' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: _____ <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit, remove wellhead & install BOP. TOH w/prod. tbg. Pour 16 sks. 12/20 Brady sand down csg. to plug back O.H. to 3665'. TIH w/pkr. set at +/- 3400'. Hydraulically fracture Eumont Yates 7RQ Zone O.H. fr. 3449' - 3665' w/190,500 gal. 60/55 constant internal phase quality foam (approx. 105,000 gal. 40# crosslinked gel & 99,288 gal. CO2) & 532,000 lbs. 12/20 Brady sand. Flow back well to clean up. Clean out fill to TD. Re-run prod. tbg. & resume flowing to sales.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Admin. Svc. Coord. DATE 5-14-97

TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 915 758-6778

(This space for State Use)

Orig. Signed by Paul Kautz Geologist TITLE _____ DATE _____

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

