

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

L CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Alpha Twenty-One Production Company 3. Address of Operator P.O. Box 1206, Jal, NM 88252 4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East THE East LINE, SECTION 22 TOWNSHIP 19S RANGE 38E NMPM.	7. Unit Agreement Name 8. Farm or Lease Name Toni 9. Well No. 1 10. Field and Pool, or Wildcat <i>Ladine Dr. Also</i>
15. Elevation (Show whether DF, RT, GR, etc.) 3604' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

5-24-85 Rigged up unit, laid down rods, and installed BOP. Pulled and tallied tubing. RIH with CIBP and set @ 6600'. RIH with tubing and circulated hole with brine water and salt gel. Set 5 sx plug on top of CIBP. Set plugs as follows:

5-28-85 25 sx plug @ 3363' - 3111'
25 sx plug @ 1726' - 1474'
25 sx plug @ 484' - 232'
10 sx plug @ surface

5-30-85 Erected dry hole marker, cleaned location of surface equipment, cut off anchors, and filled in cellar.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *R. W. Lanford* TITLE VP/Energy Resources DATE 6-19-85

APPROVED BY *R. Asadler* TITLE OIL & GAS INSPECTOR DATE JUL 26 1985

CONDITIONS OF APPROVAL, IF ANY: