

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-29410

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
South Hobbs (GSA) UNIT

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Amoco Production Company

8. Well No.
200

3. Address of Operator
P.O. Box 3092 Houston, TX 77253

9. Pool name or Wildcat
Hobbs Grayburg SAN ANDRES

4. Well Location
Unit Letter G : 2310' Feet From The North Line and 2310 Feet From The EAST Line
Section 6 Township 19-S Range 38-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3643 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MI RUSU 7-12-89 POH w/Prod EQUIP. TIN w/4 3/4" B.T AND 5 1/2"
Scraper TAG 4163 C.O. Fill 4175'. TOH w/BIT AND TIN w/2 7/8"
AND 5 1/2 - .4' spaced Howco PPI PKR. Acidize 4067' - 4175' w/5450
gal 20% HCL RDSU 7-16-89 RETURN WELL TO PRODUCTION

BWD : 8 oil 8 WATER 8 GAS
ADD : 13 oil 45 WATER 10 GAS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Blake T. Steele TITLE Admin. Analyst DATE 8-28-89

TYPE OR PRINT NAME BLAKE T. STEELE TELEPHONE NO. 713-584-7322

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 5 1989