

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR. DATE
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL = CAS WELL ☒ OTHER

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL. Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

5. PERMIT NO.

API # 30-025-30688

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

360' GR

5. LEASE DESIGNATION AND SERIAL NO.

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLM, AND
SURVEY OR AREA

12. COUNTY OR PARISH 13. STATE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRAC TREAT

SCIPLE COMPLETE

FRAC TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

HANGE PLANS

(Other)

NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DRILL, REPAIR OR COMPLETED OPERATIONS. (Indicate state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12/6 5180' TOOH. 300'/12-3/4. DOLO. 3/4" @ 4965', 3/4" @ 5180'. MUD: 8.6, 27 - - 10.5, 12,000. TD 12-1/4" HOLE TO 5180' @ 8:00 PM 12-6-89. POOH, RAN GR CML LOG FRM 3159' TO SURF. TIH, CIRC 2 HRS. POOH TO RUN 9-5/8" CSG, INCOMP.

12/7 5180' NU BOP WOC. POOH. R&C 117 JTS + 1 PC (5157') 9-5/8" 40# N-80 SIDEROA BRD LT&C NEW CSG @ 5180', CMT'D W/600 SXS CLASS "H" CMT W/5# GILSONITE, 1/2# FLOCELE, 3# SALT @ 12.7 PPG F/B 200 SXS CLASS "C" W/1/2# FLOCELE @ 14.8 PPG. DISPLACED CMT W/386 BFW @ 10 BPM @ 0-1000 PSI. BMD PLUG W/1500 PSI. FLOAT HELD OK. CIP & JC @ 4:30 PM 12-7-89. DROPPED OPENING BOMB, OPENED DV TOOL @ 3197'. CIRC 220 SXS CMT. CIRC THUR DV TOOL FOR 6 HRS. CMT'D 2ND STG THRU DV TOOL W/500 SXS CLASS "H" W/1/2# FLOCELE, 3# SALT @ 12.7 PPG F/B 200 SXS CLASS "C" W/1/2# FLOCELE @ 14.8 PPG. DISPLACED CMT W/243 BFW @ 10 BPM @ 0-1100 PSI. BMD PLUG & CLOSED DV TOOL W/2500 PSI. CIRC 125 SXS CMT. CIP & JC @ 11:30 PM 12-7-89. SET SLIPS, CUT OFF 9-5/8 CSG. WOC, NU, INCOMP.

12/8 5180' DRLG CMT. MUD: 8.6, 28. NU BOP'S YELLOW JACKET BOP'S & CK MANIFOLD TO 5000 PSI, OK. TIH W/BIT TO 3180'. TSTD 9-5/8" CSG TO 1000 PSI, OK. DRLD 10' CMT & DV TOOL. TIH TO TOC @ 5080'. PRES TSTD 9-5/8" CSG & DV TOOL TO 1000 PSI, OK. DRLD CMT, FLOAT COLLAR TO 5140', INCOMP.

12/9 5635' DRLG. 455'/22-3/4. DOLO & SD. MUD: 8.4, 27 - - 10.5. DRLD CMT & FLOAT EQUIP. DRLG NEW FORM @ 6:15 AM 12-9-89.

18. I hereby certify that the foregoing is true and correct

SIGNED Charlotte Beese

TITLE Drilling Clerk

DATE 12-12-89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side