

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-30930

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
~~Fina State~~ E 1638

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

Fina State

2. Name of Operator  
Xeric Oil & Gas Co.

8. Well No.  
1

3. Address of Operator  
P.O. Box 51311 Midland, Texas 79710

9. Pool name or Wildcat  
Queen  
Pearl Seven Rivers (South)

4. Well Location  
Unit Letter L : 1650 Feet From The South Line and 330 Feet From The West Line

Section 31 Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
GL-3707

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10/22/91 Set 5 1/2 CIBP @ 4750' and cap w/35 sx "C" cmt. TOC @ 4400'
- 10/22/91 Circulate csg. w/115 BBLs 10# brine w/1/2 sx salt gel per BBL.
- 10/24/91 Cut 5 1/2 csg. @ 2500'
- 10/24/91 Spot 45 sx @ 2550 and tag @ 2438'
- 10/24/91 Spot 50 sx @ 1865' and tag @ 1681'
- 10/25/91 Spot 15 sx from 30' to surface
- 10/25/91 Weld on steel plate w/dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Louie French TITLE P&A Supervisor DATE 10/25/91

TYPE OR PRINT NAME Louie French TELEPHONE NO. (915) 563-280

(This space for State Use)

APPROVED BY Styke F. Turner TITLE OIL & GAS INSPECTOR DATE DEC 28

CONDITIONS OF APPROVAL, IF ANY:

R 1 8

J c

RECEIVED

NOV 04 1991

ONE  
HOURS OFFICE