N.M. OIL CONS. COMMISSION P.O. BOX 1980 HOBBS, NEW MEXICO 88240

Form 3160-5 (June 1990)		ITED STATES NT OF THE IN TERI OR	FORM APPROVED Budget Bureau No. 1004-0135
		LAND MANAGEMENT	Expires: March 31, 1993
	ZONZAO OI	CAND MANAGEMENT	5 Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS			Nm 40406
Do not u	use this form for proposals to d Use "APPLICATION FO	6 If Indian, Allottee or Tribe Name	
1 Type of W	SUBMI	7. If Unit or CA, Agreement Designation	
Oil Well Name of O	X Gas Well Other	8. Well Name and No.	
			Quietman Federal#1
Collins & Ware, Inc. 3 Address and Telephone No.			9. API Well No.
303 W.Wall. Ste. 2200. Midland TX 79701			30-025-31714 10. Field and Pool, or Exploratory Area
303 W. Wall, Ste. 2200, Midland, TX 79701 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			
K, 1980' FSL & 1980' FWL			Quail Ridge Morrow 11. County or Parish, State
Sec. 6, T20S, R34E			The County of Fallshi, State
		Unit K	Lea NM
	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION			
	Notice of Intent	Abandonment	Change of Plans
	r X i	Recompletion	New Construction
İ	Subsequent Report	Plugging Back	Non-Routine Fracturing
1		Casing Repair	Water Shut-Off
	Final Abandonment Notice	Altering Casing	Conversion to Injection
		Other	Dispose Water
13 Describe De			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give sul	posed or Completed Operations (Clearly state all bsurface locations and measured and true vertice	pertinent details, and give pertinent dates, including estimated date of starting all depths for all markers and zones pertinent to this work.)*	my proposed work. If well is directionally drilled,
12-1-93: Pull production equipment; set CIBP @ 6320'. Circulate hole w/ 9.5# mud and spot 35sxcement plug on top of CIBP. Spot 35 sx plug from 5250-4940. Spot 35 sx plug from 3244-2934'. Cut off approx. 1500'/ 5 1/2" csg. Pulled 34 jts./ 5 1/2" 17# csg. Spot 35 sx plug over csg. stub from 1650-1369'. Tag plug @ 1368' and spot 35 sx. plug from 547-237', and cement plug from 175' to surface. Weld on dry hole marker. FINAL REPORT: WELL P & A.			
			ARREST TO THE CONTROL OF THE CONTROL
			© 2)
			FTI
			(n 1/2)
			29
		Approved as to plugging of the well bord,	E G
		Liability under bond is retrial 1 until	_
		surface restoration is completed,	
14 I hereby Arti	fy that the foregoing is true and correct		
. 🔽	3	D 1	
Signed	Max Guerry	Regulatory Mgr.	
Approved by	or Federal or State office use) (ORIG. SGD.) JOE G. L. approval, if any:	ARA Tide PETROLEUM ENGINEER	Date 12/14/43