

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.  
Santa Fe, NM 87505

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. <b>30-025-32835</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Byrd Gas Com</b>
8. Well No. <b>9</b>
9. Pool name or Wildcat <b>Eumont Yates SRQ Gas</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
**ARCO Permian**

3. Address of Operator  
**P.O. Box 1089 Eunice, NM 88231**

4. Well Location  
Unit Letter **G** : **1650** Feet From The **N** Line and **2310** Feet From The **E** Line  
Section **11** Township **20S** Range **36E** NMPM **Lea** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**3574'**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <b>Add Eumont Perfs</b> <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 3700' PBD: 3649' PERFS: 2527-3088' (new) 3363-3540' (old)

05/06/99: MIRUPU. POH w/rods & pmp. NUBOP. RIH w/bit & scraper. Run & set RBP @ 3250'. Load & tst csg to 400#, held OK.

05/07/99: Pickle tbg & csg w/1000 gals 15% HCL

05/10/99: Perf Eumont interval 2527-3088' w/1 JSPF, 25 shots.

05/11/99: PPI acidize 2527-3088' w/2000 gals 15% HCL acid.

05/12/99: Frac 2527-3088' w/70 tons CO2 followed by 102,300# 12/20 resin coated sand. Flush w/98 MCF nitrogen.

05/24/99: RIH w/tool & retrieve RBP @ 3250'. 2-3/8" tbg set @ 3607'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 08/04/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for SIGNATURE)  
ORIGINAL SIGNED BY  
GARY WINK  
FIELD REP. II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 8-16-99

CONDITIONS OF APPROVAL, IF ANY:

5

1