

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
811 S. 1st Street, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-35554
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	SOUTH HOBBS (G/SA) UNIT
8. Well No.	245
9. Pool name or Wildcat	HOBBS (G/SA)
10. Elevation (Show whether DP, RKB, RT GR, etc.)	3610GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)

1. Type of Well:	Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator	Occidental Permian Ltd.
3. Address of Operator	1017 W. Stanolind Rd., HOBBS, NM 88240 505 397-8200
4. Well Location	Unit Letter <u>P</u> : <u>1303</u> Feet From The <u>SOUTH</u> Line and <u>708</u> Feet From The <u>EAST</u> Line Section <u>4</u> Township <u>19S</u> Range <u>38E</u> NMPM <u>LEA</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>Re-Completion</u> <input checked="" type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP over San Andres perms at ±4075.
- Perforate Grayburg.
- Acid and Frac stimulate.
- Run production equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PROD ENGR DATE 4/9/01
 TYPE OR PRINT NAME D. NELSON TELEPHONE NO. 505-397-8200

(This space for State Use)

APPROVED BY _____ TITLE PETROLEUM ENGINEER DATE 4/9/2001
 CONDITIONS OF APPROVAL IF ANY: _____