

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Exxon Corporation | 8. Farm or Lease Name Paddock Unit |
| 3. Address of Operator P. O. Box 1600, Midland, Texas 79701 | 9. Well No. 5 |
| 4. Location of Well UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>S</u> LINE AND <u>1980</u> FEET FROM THE <u>E</u> LINE, SECTION <u>35</u> TOWNSHIP <u>21-S</u> RANGE <u>R-37-E</u> NMPM. | 10. Field and Pool, or Wildcat Paddock |
| 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|---|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input checked="" type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was shut-in during September, 1974 due to mechanical problems. Future disposition will be dependent upon results of pilot waterflood which is now in progress. Evaluation of pilot flood will be complete by year end 1977.

Efficient 10/1/74

"The condition of the well is such as to prevent damage to the producing zone, migration of hydrocarbons or water, the contamination of fresh water or other natural resources, or the leakage of any substance at the surface."

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A L Clemmer TITLE D. L. CLEMMER DATE SEP 25 1975
UNIT HEAD

APPROVED BY John Runyan TITLE Geologist DATE 001
Geologist

CONDITIONS OF APPROVAL, IF ANY: