

APR 20 1937

AREA 640 ACRES
LOCATE WELL CORRECTLY

WELL RECORD

DUPLICATE

Mail to Oil Conservation Commission, Santa Fe, New Mexico, or its proper agent not more than twenty days after completion of well. Follow instructions in the Rules and Regulations of the Commission. Indicate questionable data by following it with (?). SUBMIT IN TRIPLICATE.

Continental Oil Company Box CC, Hobbs, New Mexico
Company or Operator Address
State D-15 Well No. **8** in **SE/4** of Sec. **15**, T. **21-S**
Lease
R. **36-E**, N. M. P. M., **Bunies** Field, **Lea** County.
Well is **4620** feet south of the North line and **660** feet west of the East line of **Sec. 15**
If State land the oil and gas lease is No. **13017** Assignment No. _____
If patented land the owner is _____, Address _____
If Government land the permittee is _____, Address _____
The Lessee is _____, Address _____
Drilling commenced _____ 19____ Drilling was completed _____ 19____
Name of drilling contractor **Trinity Drlg. Co.**, Address **Dallas, Texas**
Elevation above sea level at top of casing **3574** feet.
The information given is to be kept confidential until _____ 19____

OIL SANDS OR ZONES

No. 1, from **3805** to **3854** No. 4, from _____ to _____
No. 2, from _____ to _____ No. 5, from _____ to _____
No. 3, from _____ to _____ No. 6, from _____ to _____

IMPORTANT WATER SANDS

Include data on rate of water inflow and elevation to which water rose in hole.

No. 1, from _____ to _____ feet.
No. 2, from _____ to _____ feet.
No. 3, from _____ to _____ feet.
No. 4, from _____ to _____ feet.

CASING RECORD

SIZE	WEIGHT PER FOOT	THREADS PER INCH	MAKE	AMOUNT	KIND OF SHOE	CUT & FILLED FROM	PERFORATED FROM TO	PURPOSE
10-3/4	40.50#	8	SH LW	238'0"	TP			
7-5/8	26.40#	10	Smls	1486'0"	Cement guide shoe			
5-1/2	17#	10	Smls	3685'11"	Cement guide shoe & float collar			
2"	4.70#		Smls	3848'6"				

MUDDING AND CEMENTING RECORD

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	MUD GRAVITY	AMOUNT OF MUD USED
15"	10-3/4"	245'	225	Halliburton		
9-5/8	7-5/8"	1413'	425	do		
6-3/4	5-1/2"	3686'	425	do		
2"		3840'				

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth Set _____
Adapters—Material _____ Size _____

RECORD OF SHOOTING OR CHEMICAL TREATMENT

SIZE	SHELL USED	EXPLOSIVE OR CHEMICAL USED	QUANTITY	DATE	DEPTH SHOT OR TREATED	DEPTH CLEANED OUT

Results of shooting or chemical treatment _____

RECORD OF DRILL-STEM AND SPECIAL TESTS

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto.

TOOLS USED

Rotary tools were used from **0** feet to **3854** feet, and from _____ feet to _____ feet
Cable tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet

PRODUCTION

Put to producing **April 16, 1937**, 19____
The production of the first 24 hours was **2376** barrels of fluid of which **100** % was oil; _____ % emulsion; _____ % water; and _____ % sediment. Gravity, Be _____
If gas well, cu. ft. per 24 hours **1,360,000** Gallons gasoline per 1,000 cu. ft. of gas _____
Rock pressure, lbs. per sq. in. _____

EMPLOYEES

Dan Hillin, Driller **E.C. Sterling**, Driller
H.D. Wilson, Driller _____, Driller _____

FORMATION RECORD ON OTHER SIDE

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far as can be determined from available records.

Subscribed and sworn to before me this **18th****Hobbs, N.M.** April **17, 1937**day of **April**, 19____Name **Chas P. Allen**Position **A. District Supt.**Representing **Continental Oil Company**My Commission expires **October 24, 1939**Address **Box CC, Hobbs, N.M.**

DOI: 10.1002/eqm2

1220 Redrock & shells
1340 Redrock
1455 Ambergris

01 SANDS OR ZONES

14-00000

14-00000