

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
B-935

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
2. Name of Operator: **EXXON CORPORATION**
3. Address of Operator: **P.O. BOX 1600, MIDLAND, TEXAS 79701**
4. Location of Well: UNIT LETTER **B**, **660** FEET FROM THE **NORTH** LINE AND **1980** FEET FROM THE **EAST** LINE, SECTION **26** TOWNSHIP **21-S** RANGE **36-E** NMPM.
7. Unit Agreement Name: **EUMONT YATES SEVEN RIVERS**
8. Farm or Lease Name: **NEW MEXICO "G" STATE**
9. Well No.: **18**
10. Field and Pool, or Wildcat: **EUMONT YATES SEVEN RIVERS**
15. Elevation (Show whether DF, RT, GR, etc.): **3563 DF**
12. County: **LEA**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER _____	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-18-76, MIRU CSG PULLERS, PLD. RODS & PUMP, SPOT 30 SX CNT PLUG @ 3820' W.O.C., TAGGED PLUG @ 3690', LOAD CSG W/MUD LADED BR, SPOT 20 SX CNT PLUG @ 2800', W.O.C., TAGGED PLUG @ 2690'. LAID DN TBG, WELD ONTO 5 1/2" CSG, WORKED PIPE, SPOT 5 1/2" CSG @ 2675', UNABLE TO WORK LOOSE, SHOT PIPE @ 1566, WORED FREE, LAID DOWN 41 JTS 5 1/2" CSG, RAN 2 7/8" TBG IN HOLE TO 1612', SPOT 20 SX CNT PLUG, WOC, TAGGED CNT. @ 1373' SPOT 35 SX CNT PLUG @ 350', TAGGED PLUG @ 245'. SPOT 10 SX PLUG @ SURFACE, LAID DOWN TBG, REMOVED WELL HEAD. INSTALLED DRY HOLE MARKER. FRW 8-18-76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A.L. Clemmer TITLE UNIT HEAD DATE 8-30-76

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: