

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.O.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator  
SHELL WESTERN E&P INC.

3. Address of Operator  
P.O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. Location of Well  
UNIT LETTER J 3546 FEET FROM THE NORTH LINE AND 1650 FEET FROM THE EAST LINE, SECTION 3 TOWNSHIP 21-S RANGE 37-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name  
TAYLOR GLENN

9. Well No.  
5

10. Field and Pool, or Wildcat  
WANTZ ABO

11. Elevation (Show whether DF, RT, GR, etc.)  
3488' DF

12. County  
LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

| NOTICE OF INTENTION TO:                        | SUBSEQUENT REPORT OF:                                                             |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>                                            |
| TEMPORARILY ABANDON <input type="checkbox"/>   | COMMENCE DRILLING OPNS. <input type="checkbox"/>                                  |
| PULL OR ALTER CASING <input type="checkbox"/>  | CASING TEST AND CEMENT JOB <input type="checkbox"/>                               |
| PLUG AND ABANDON <input type="checkbox"/>      | OTHER <u>PB HARE SIMPSON, RECMPLTD TO ABO</u> <input checked="" type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/>          | ALTERING CASING <input type="checkbox"/>                                          |
| OTHER <input type="checkbox"/>                 | PLUG AND ABANDONMENT <input type="checkbox"/>                                     |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

3-10-86: Pulled production equipment.

3-11-86: Ran CCL/GR & CNL/GR logs from 7966' to 6700'. Set CIBP @ 7850' & capped w/35' cmt.

3-12-86: Spotted 150 gals 15% HCl-NEA from 7270' - 7120'. Perf'd Wantz Abo 7124' - 7256' (4 JSPF, 136 holes).

3-13-86: Acd perfs 7124' - 7256' w/6000 gals 15% HCl-NEA + 30% CO<sub>2</sub> + 200# rock salt. Flow tstd well.

3-20-86: Installed production equipment and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MAY 19, 1986

APPROVED BY Eddie W. Seay Oil & Gas Inspector DATE MAY 22 1986

DATE OF APPROVAL IF ANY: 2A Hare Simpson E

RECEIVED  
MAY 22 1986  
HOBBS OFFICE