

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON PERFORATING (Other) 5-1/2" CSG. LINER	X

January 6, 1955

(Date)

Hobbs, New Mexico

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Shell Oil Company

(Company or Operator)

Taylor Glenn

(Lease)

Lane Wells

(Contractor)

Well No. 5 in the Lot 10 1/4 of Sec. 3

T -21-8, R-37-E, NMPM, Hare Pool, Lea County.

The Dates of this work were as follows: January 6, 1955

Notice of intention to do the work (was) ~~received~~ submitted on Form C-102 on January 5, 1955,

(Cross out incorrect words)

and approval of the proposed plan (was) ~~received~~ obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Perforated 5-1/2" casing liner opposite the Mc Kee Sand from 7924' - 7960'
with six 15/32" Type "E" bullet shots per foot.

Witnessed by H. B. Leach

(Name)

Shell Oil Company

(Company)

Production Foreman

(Title)

Approved:

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Original signed by

Name F. D. Leigh

F. D. Leigh

Position Division Mechanical Engineer

Representing Shell Oil Company

Address Box 1957, Hobbs, New Mexico

(Title)

(Date)