(November 1983) (Formerly 9-331)	DEPARTM NT OF T BUREAU JF LAND	HE INTERIOR	(Other instructions o verse side)	5. LEASE DESIGNATION AND SERIAL NO.
CUNIDI			DEAGNIE	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS 100 (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)				10
OIL GAS WELL WELL	SIRTO	MAR	13 9 22 17 18	NORTHEAST DRINKARD UN
SHELL WESTERN 3. ADDRESS OF OPERATOR	E&P INC.	A(c)		NORTHEAST DRINKARD UN
P 0 BOX 576.		77001 (WCK 44	35)	410
1. LOCATION OF WELL (Repo See also space 17 below.) At surface	rt location clearly and in acco		requirements.*	10. FIELD AND POOL OF KILDCAT NORTH EUNICE BLINEBRY TUBB-DRINKARD OIL & G. 11. SEC., T., E., M., OR BLK. AND SURVEY OF AREA
*				SEC. 10, T21S, R37E
4. XXXXXXXX API NO.	15. ELEVATIONS	(Show whether DF, RT, G	R. etc.)	12. COUNTY OR PARISH 13. STATE
30-025-06453	3427'	DF	·.	LEA NM
6.	Check Appropriate Box	To Indicate Nature	e of Notice, Report,	or Other Data
NOTI	ICE OF INTENTION TO:			BSEQUENT REPORT OF:
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CA MULTIPLE COMPLE ABANDON* CHANGE PLANS	TE	Completion or Re-	std Abo abandonment solute of multiple completion on Well completion Report and Log form.)
proposed work. If we nent to this work.) •	il is directionally drilled, give	subsurface locations a	nd measured and true v	iates, including estimated date of starting an ertical depths for all markers and zones pert
•		D @ 6671'.	. Set pkr @	6650'. Pres tstd
Abo abandoni	nent to 1000 #, 1	held OK. Rav	GR/CNL/CCL	from 6670' to 5550'.
	,		•	F). Acd perfs 5707'-
	70 gals 15% HCI			
			•	
•				
8. I hereby certify that the	foregoing is true and correct W.F.N. KELLDOF	*	RODUCTION ENGI	NEER DATE 3-09-89
(This space for Federal of	or State office use)			•
APPROVED BY SEC. S	CD) DAYD E GLA	SS	· .	DATE

*See Instructions on Reverse Side