SANTA FE, NEW MEXICO

CELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of

Indicate na	sture of noti	ice by checking belo	w:		
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	x	NOTICE OF INT	ENTION 7	O SHOOT OR	
OTICE OF INTENTION TO CHANGE PLANS	-	NOTICE OF INT	ENTION 1	O PILL OR	
OTICE OF INTENTION TO REPAIR WELL		NOTICE OF INT			<u>.                                    </u>
OTICE OF INTENTION TO DEEPEN WELL					
	Ho.	bbs, New Mexic	10	January 2	. ∥ 1, 1952
IL CONSERVATION COMMISSION, anta Fe, New Mexico entlemen:		Place		Date	
llowing is a notice of intention to do certain w	ork as desc	ribed below at the			
Shell 011 Company La Company or Operator L	-0000		Well	No5	in SW 40
Sec. 3 , T. 21-S , R	37-B N	V. M. P. M	Drinkard		Total
LeaCoun	aty.				
FULL DETAILS	OF DDOE	OCED DI AM O	S IIIODYr		
FOLLOW INSTRUCTIONS IN THE					
			o or the		
Ran 13-3/8" casing and coment					
Ran 13-3/8" casing and cement	ted at 2	18' with 250 a	naka of	ment Cine	waated
out 77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	ruhated
Ran 13-3/8" casing and cement out 35 sacks of cement. Plugwill test casing.	ted at 2	18' with 250 a	naka of	ment Cine	rukat ed
out 77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	ruhat ed
eut-77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	suitated
aut 77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	eulated
aut 77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	sulated
eut-77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	sulated
eut-77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	sulated
aut 77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	sulated
aut 77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	eulated
eut-77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	sulated
eut-77 sacks of cement. Plug	ted at 2	18' with 250 a	naka of	ment Cine	su <b>hat e</b> d
will test casing.	ted at 2	18' with 250 a	naka of	ment Cine	suited
will test casing.	ted at 21 g down 2:	18' with 250 s.:30 AM 1-19-52	neks of	neat. Circ	eulated
will test casing.	ted at 21 g down 2:	18' with 250 s.:30 AM 1-19-52	acks of After	ment Cine	eulated
will test casing.	ted at 21 g down 2:	18' with 250 s.:30 AM 1-19-52	acks of After	meat. Circ WOC 24 hrs	Lla
will test casing.	ted at 21 g down 2:	18' with 250 s.:30 AM 1-19-52  By	Shell Oi Comp	meat. Circ WOC 24 hrs	S. S
will test casing.	ted at 21 g down 2:	18' with 250 s.:30 AM 1-19-52  By	Shell O1 Compose E. Sl.	Company Sany or Operator Sigle L. Company Sany or Operator Signed Sangle	S. S
will test casing.	ted at 21 g down 2:	18' with 250 s.:30 AM 1-19-52  By	Shell O1 Composition Communication	Company Sany or Operator Sigle L. Company Sany or Operator Signed Sangle	Lla