

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTHEAST DRINKARD UNIT
8. Well No. 606
9. Pool name or Wildcat N. EUNICE BLINEBRY-TUBB-DRNKRD
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3775' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Shell Western E&P Inc.
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCH 4435)
4. Well Location Unit Letter F : 3375 Feet From The SOUTH Line and 3225 Feet From The EAST Line Section 15 Township 21S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3775' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: SI TO EVAL CSG LK <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-03 TO 5-10-91:

POH W/PROD EQMT. HIT TI SPOT IN CSG WHILE PULLING TBG. CO TO TI SPOT @ 4112' W/ SCRPR. COULD NOT GET BELOW. ATT TO ESTAB CIRC, COULD NOT. DRY DRILL SCALE FROM 4112' TO 4130', FELL FREE. TAG FILL @ 6662', POH. RIH W/BIT & SCRPR. RETAG FILL @ 6658'. MLD THRU TI SPOT @ 3995', FELL FREE @ 4065'. PT SQZD PADDOCK PERFS 5130-50' TO 500#, HELD. PT BACKSIDE TO 520#, LOST 140# IN 10 MIN. PT SA SQZD SA PERFS 4052' - 4878' TO 500#, LOST 300# IN 15 MIN. PT BACKSIDE TO 500#, HELD. POH W/TBG & TOOLS. SI WELL PENDING EVAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 7/26/91  
TYPE OR PRINT NAME J. H. SMITHERMAN TELEPHONE NO. 713/870-3797

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 01 1991

GR-  
HOBBS CANOPY