NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. It copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

| ional instructions in the Rules and Regulat | Indicate Nature of Notice | e by Checki | ng Helow | | | | |
|---|--|-------------|---------------------------|---------------------------------------|-------------------------------------|----------------------------------|----------------------------|
| SOTICE OF INTENTION O CHANGE PLANS | Notice of Intention to Temporarily Abandon W | Vell. | | orige of Drill D | Intention Deeper | | |
| OTICE OF INTENTION O PLUG WELL | Notice of Intention to Plug Back | | | otice of Set Lin | înt en tion Br | | |
| OTICE OF INTENTION D SQUEEZE | Notice of Intention to Acidize | | | отіа в о ў о Ѕн оо т | Intention (Nitro) | | |
| OTICE OF INTENTION OF GUN PERFORATE | Notice of Intention (Other) | | 51 - | otice of Other) | Intention | | |
| IL CONSERVATION COMMISSION ANTA FE, NEW MEXICO | Roswell | . New Me | xico | • / | | rember | 7, 1960 |
| entlemen: | | | | | | | |
| Following is a Notice of Intention to d | | | | | | | |
| (Company or Operato | ny r) | Lease | W | ell No | | in | (Unit) |
| NW /4 SW /4 of Sec. 1: | l , _T 22S , _R | 37E N | мрм., | | Paddock | <u>C</u> | Po: |
| (FOLLOV 1. Treat down tubing w, reducing chemical. | LL DETAILS OF PROPO VINSTRUCTIONS IN TH | E RULES | AND REG | ULATio | | a frict | tion |
| FUI (FOLLOW) 1. Treat down tubing way, reducing chemical. | LL DETAILS OF PROPOSITIONS IN THE 15% N | E RULES | AND REG | ULATio | | a frict | tion |
| FUI (FOLLOW 1. Treat down tubing w, reducing chemical. 2. Swab load. 3. Place on production. | LL DETAILS OF PROPOSITIONS IN THE 15% N | E RULES A | AND REG | ULATIO i conti | mining a | | |
| FUI (FOLLOW 1. Treat down tubing w, reducing chemical. 2. Swab load. 3. Place on production. | LL DETAILS OF PROPOSITIONS IN THE STATE OF THE STAT | E RULES | AND REG | Company | ny or Cperator |)riginal | tion Signed By OWERY |
| FUI (FOLLOW 1. Treat down tubing w, reducing chemical. 2. Swab load. 3. Place on production. | LL DETAILS OF PROPO V INSTRUCTIONS IN TH | E RULES | ell Oil | Company | ny or Cperator | Driginal B. A. Le | Signed B y OWERY |
| FUI (FOLLOV 1. Treat down tubing w, reducing chemical. 2. Swab load. 3. Place on production Approved Except as follows: | LL DETAILS OF PROPO V INSTRUCTIONS IN TH /5000 gallons 15% N | Showy R. | ell Oil A. Low Send Con | Company Exploi | ny or Cperator tation ons regarding |)riginal R. A. L. Engine | Signed B y OWERY |