

**ATTACHMENT TO FORM C-105
COLLINS & WARE, INC.
E.W. WALDEN #2**

26. Perforation Record

Drinkard	6425 - 6460 (140 shots)	5/47	2A
Blinebry	5483 - 5605 (28 shots)	3/75	
Drinkard	6262 - 6376 (32 shots)	3/75	2A
	3179 (2 holes)	7/75	
Blinebry	5677 - 5877 (50 holes)	1/97	

27. Treatment Record

6425 - 6460	Treated with 500 gals of Western mud acid.	5/47
6425 - 6460	AT with 3000 gals 15% NE acid using 300# 50/50 Benzoic flakes and moth balls mixed in 10 bbls oil.	3/74
6410	Set CIBP with 2 sx cement on top.	3/75
6262 - 6376	AT with 6200 gals 15% XF-38 acid.	3/75
5483 - 5605	AT with 5000 gals 15% Kleen-Flo acid.	3/75
3500	Set RBP at 3500' with 4 sx sand on top.	
3179	Squeezed with 125 sx cement.	7/75
5483 - 5605	FT with 32,000 gals YF 1 1/2 G Frac fluid, 15,000# 100 mesh sand, 50,000# 20/40 sand.	8/75
6200	Set CIBP at 6200' with 35' of cement on top.	1/97
5677 - 5877	AT with 2000 gals 15% Ferchek acid.	1/97
5677 - 5877	FT with 98,000 gals Delta-Frac 25 carrying 275,000# sand.	1/97