

NO. OF COPIES RECEIVED		
DISTRIBUTION		
DATE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
5. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name E.W. Walden
3. Address of Operator Drawer "D", Monument, New Mexico 88265	9. Well No. 1 2
4. Location of Well UNIT LETTER K, 2009 FEET FROM THE South LINE AND 1911 FEET FROM THE West LINE, SECTION 15 TOWNSHIP 22-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to: Run Gamma Ray Neutron log from 2700' to 6465'. Set CIBP above present Drinkard zone perforations at approx. 6425' with 2 sacks cement on top of plug. Perforate Drinkard zone (gas section) and Blinbry Gas zone subject to logs. Acidize and frac both zones as required. Run production equipment and dual complete in Blinbry gas and Drinkard zones.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>[Signature]</u>	TITLE <u>Supver., Admin. Services</u>	DATE <u>3-14-75</u>	
APPROVED BY <u>Joe D. [Signature]</u>	TITLE <u>Joe I. [Signature]</u>	DATE <u>7</u>	
CONDITIONS OF APPROVAL, IF ANY:			