NEW MEXICO OIL CONSERVATION COMMIS	SION
NEW MEXICO OIL CONSERVATION COMMIS  Santa Fe, New Mexico  MISCELLANEOUS NOTICES	
MISCELLANEOUS NOTICES	

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

ional instructions in the Rules		T	Madica be Cha			
		Indicate Nature of	Moreon by Che			
OTICE OF INTENTION O CHANGE PLANS		Notice of Intentic Temporarily Aban	on to Idon W <b>el</b> l		NOTICE OF INTENTION TO DRILL DEEPER	
OTICE OF INTENTION O PLUG WELL		Notice of Intention to Plug Back	on		Notice of Intention to Set Lines	
otice of Intention		Notice of Intention To Acidize	ON	x	Notice of Intention to Shoot (Nitro)	
OTICE OF INTENTION O GUN PERFORATE	x	Notice of Intentic (Other)	NON		Notice of Intention (Other)	
IL CONSERVATION COMP ANTA FE, NEW MEXICO	MISSION	Midland, T	rexas		October 18, 1960	)
entlemen:			(FIRCE)			
Following is a Notice of Ir	tention to d	lo certain work as desc	ribed below at	the		••••••••••••••••••••••
Campbell & Hedri	lck	(	Christmas		Well No1	nja in
(Comp	any or Operato	er) 22_5	37_E		Drinkard	(Onic)
After testing 7%	FU: FOLLOV casing p	LL DETAILS OF I W INSTRUCTIONS I clan to log and two shots per fo	PROPOSED IN THE RUL	PLAN C es and Drink	Drinkard  Drinkard  OF WORK  REGULATIONS)  ard zone approxima tubing and acidize	te:
After testing 7% interval 6310-652	FU: FOLLOV casing p	LL DETAILS OF I W INSTRUCTIONS I clan to log and two shots per fo	PROPOSED IN THE RUL	PLAN C es and Drink	OF WORK REGULATIONS) ard zone approxima	te:
After testing 7% of interval 6310-6520	FUI (FOLLOW casing p 0 with t 15% N.E	LL DETAILS OF I W INSTRUCTIONS I clan to log and two shots per fo	PROPOSED IN THE RUL perforate oot, run 2	PLAN C es and Drink	OF WORK REGULATIONS) ard zone approxima tubing and acidize	te:
After testing 7% interval 6310-6520 with 5000 gallons	FUI (FOLLOW casing p 0 with t 15% N.E	LL DETAILS OF E W INSTRUCTIONS I clan to log and two shots per for	PROPOSED IN THE RUL perforate oot, run 2	PLAN C es AND Drink EUE	of WORK REGULATIONS) ard zone approximate tubing and acidize tubing and acidize  tubing and acidize	te.
After testing 7% interval 6310-6520 with 5000 gallons  Approved	FUI (FOLLOW casing p 0 with t 15% N.E	LL DETAILS OF E W INSTRUCTIONS I clan to log and two shots per for	PROPOSED IN THE RUL perforate oot, run 2	PLAN C ES AND Drink EUE	of WORK REGULATIONS)  ard zone approximatubing and acidize  tubing and acidize  all & Hedrick  sympany or Operator  All All All  or	te.