

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-10396
5. Indicate Type of Lease F2X STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> WIW	7. Lease Name or Unit Agreement Name Langlie Mattix Penrose San Unit
2. Name of Operator Anadarko Petroleum Corp.	8. Well No. 5A-1
3. Address of Operator P.O. Box 2497; Midland, TX 79702	9. Pool name or Wildcat Langlie-Mattix SR QN GRBG
4. Well Location Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 22 Township 22S Range 37E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3372' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-25-97 Notified Bonnie @ OCD & Vince @ BLM. MIRU. POOH w/ injection tbg. RIH w/ 7" CICR to 3340'. SDFN.

8-26-97 Contacted Bonnie @ OCD & Vince @ BLM. Established rate thru CICR and squeezed 200 sx C cmt; pumped 10 sx C cmt 3340-3281'. Circulated hole and pumped 28 sx C cmt 2450-2283'. Perforated @ 1250', set packer; no rate. Gary Wink w/ OCD on location. POOH w/ packer and pumped 50 sx C cmt 1300-1003'. Perforated @ 250', squeezed 295 sx C cmt and circulated to surface. RDMO.

8-30-97 Cut off wellhead & capped well. Covered pit and dug up dead men. Installed dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. Newman TITLE Engineer DATE 8-29-97
TYPE OR PRINT NAME James F. Newman, P.E. TELEPHONE NO. (915) 687-1946

(This space for State Use)

APPROVED BY Charles L... TITLE OIL & GAS INSPECTOR DATE

CONDITIONS OF APPROVAL, IF ANY:

IC 111