NEW MEXICO OIL CONSERVATION COMMISSION

FEB - 7 1951

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of

Indicate nature	of notice by checking below:		
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTEN	TION TO SHOOT OR TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENT OTHERWISE A	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENT	TION TO PLUG WELI	
NOTICE OF INTENTION TO DEEPEN WELL	NOTICE OF INTENDED	TION TO INSTALL	<u> </u>
	Midland, Texas Place	February Date	6, 1951
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico. Gentlemen: Following is a notice of intention to do certain wor	k as described below at the		
Rowan Oil Company	Cary	_Well No5	in SE/4 of NW/
Company or Operator Less of Sec. 22 , T. 22S , R. 378	ase	Carr	Field.
WOLLOW INSTRICTIONS IN THE RE	HES AND REGULATIONS	OL TUD COMMISSIC	/14
The bottom hole pressure of this well not flow. In an effort to indust 7050°, 6005° and 4785°, with a page	il has dropped, the wat	ter is increasing	g and it
The bottom hole pressure of this well will not flow. In an effort to indust 7050, 6005 and 4785, with a page	il has dropped, the water flow, we propose to acker at 70901.	ter is increasing o set gas lift va	g and it
The bottom hole pressure of this well will not flow. In an effect to indust 7050', 6005' and 4785', with a page of 1051'.	il has dropped, the water flow, we propose to acker at 70901.	ter is increasing	g and it
The bottom hole pressure of this well will not flow. In an effort to indust 7050, 6005 and 4785, with a part of the second secon	Rowan Of	ter is increasing set gas lift v	g and it
The bottom hole pressure of this well will not flow. In an effort to indust 7050, 6005 and 4785, with a part of the second secon	Rowan Of	l Company mpany or Operator n Production Supunications regarding w	g and it
The bottom hole pressure of this well will not flow. In an effort to indust 7050, 6005 and 4785, with a part of the second secon	Rowan Oi Position Division Send comm	l Company mpany or Operator m Production Supunications regarding w	g and it