

MAR 6 1961

HOBBS OFFICE COPY

Budget Bureau No. 43-B388.4
Approval expires 12-31-60.

0			

E. W. STANDLEY
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. LC-71986 B

Unit

RECEIVED

MAR 3 1961

SUNDRY NOTICES AND REPORTS ON WELLS

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hill & Meeker - Ora Hall Federal "14" January 6, 1961

Well No. One is located 2310 ft. from ^(N)~~(S)~~ line and 330 ft. from ^(E)~~(W)~~ line of sec. 14SW 1/4 of NW 1/4, Sec. 14 25S 32E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)Undesignated Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3454 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11/25/60 - Set 354' 8-5/8" casing - Cement circulated

12/ 3/60 - T.D. 4845' - No commercial oil or gas found

12/ 4/60 - Cement Plugs

10 sks @	ground level
20 sks @	360' Bottom surface cas.
20 sks @	780' Top of mustler
20 sks @	1140' Bottom of mustler
20 sks @	3480' Top of Salt
20 sks @	4760' Top of Delaware Sand

Hole full of mud laden material - Set 4" marker 4' above surface - Clean
located at 4760' and that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HILL & MEEKER

Address 519 Midland Savings &

Loan Bldg.

Midland, Texas

By

Title Production Clerk

NOTED

MAR 8 1961

GORDON

API 30-025-08181